

Nanodyne Replacement Illuminator for Nikon TE2000 - Included Items

PN 11145 T2PIHP3 Illuminator Assy  
w Offset Lens

PN 11170 Pot-Cable Assy  
(48 in long)

PN 10695 SHCS  
M3 x 0.5 x 12 mm  
(3 pcs)

PN 10718 Adapter  
Nikon Optiphot-2

PN 10467 Set Screw  
8-32 Brass Tip

If Needed see the Nikon Optiphot-2  
installation instructions for removing  
the original illuminator and attaching  
the Nanodyne one.

Additional Items Included But Not Shown:

PN 10490 Hex Key 5/64 inch (for securing illuminator to adapter)

PN 10566 Hex Key 2.5mm long arm ball end (for M3 SHCS to  
attach adapter to microscope)

The illuminator  
may be  
powered by  
plugging the  
cable into the  
power supply  
provided, or  
into a suitable  
USB port on a  
computer or  
other device.



PN 11163 Power Supply 5V 2.1A and  
PN 10734 Power Cable 1.35mm  
ID/3.5mm OD x USB A 6 ft.

Power supplies are subject to  
substitution without notice due to  
availability issues and changes in  
regulations.



PN 10736 Rubber plug to block  
unused AC power receptacle.



3M VHB tape to secure pot cable

Wayne Bonin 11/9/2020	
PN 11278 Nikon TE2000 Illuminator System	REV 6
SHEET 1 OF 1	