The illuminator may be powered by plugging the cable into the power supply provided, or into a suitable USB port on a computer or other device.



PN 11163 Power Supply 5V 2.1A and PN 10734 Power Cable 1.35mm ID/3.5mm OD x USB A 6 ft.

Power supplies subject to substitution without notice due to availability issues and changes in regulations.



PN 10736 Rubber plug to block unused AC power receptacle

Vayne Bonin	11/4/202	0		
N 11151 Nikon Optiphot 300 uminator System		REV 4		
5	SHEET 1 (	)F	1	

adjustment potentiometer is PN 11145 T2PIHP3 Illuminator Assy w Offset Lens - Top Adjust standard on this unit. Ask about a remote adjustment pot if desired.

PN 10695 SHCS M3 x 0.5 x 12 mm (3 pcs)

PN 10718 Adapter Nikon Optiphot-2

© Copyright 2020 Nanodyne Measurement Systems. Document authorized for installation of Nanodyne equipment only. www.nano-dyne.com Wayne Bonin 651-323-8592

Note that the illuminator mounted